



# Thank You!

---

**You have successfully downloaded your document from Workbenchmagazine.com. Below are some tips for Trouble-Free Printing**


- 1)** Clear printer memory. If you are unable to print this document, turn off your printer for at least 15 seconds and try again.
  
- 2)** Print two or three pages at a time. If clearing the printer memory didn't help, try printing only two or three pages at one time, rather than sending the entire file
  
- 3)** If a document is required to be at an accurate scale set the page scaling option to "none" in your printer settings.
  
- 4)** Get advanced printer help. Visit Adobe Support for instructions in troubleshooting common printer problems.

<http://www.adobe.com/support/techdocs/316508.html>


# DRILL PRESS TABLE CUTTING DIAGRAM

**MATERIALS LIST:**

- A (2) 1/2 x 16 x 36 BALTIC BIRCH
- B (1) 1/2 x 12 x 34 BALTIC BIRCH
- C (2) 1/2 x 12 x 10 1/4 BALTIC BIRCH
- D (4) 1/2 x 12 x 4 3/4 BALTIC BIRCH
- E (4) 1/2 x 3 15/16 x 9 3/16 BALTIC BIRCH
- F (4) 1/2 x 3 15/16 x 11 1/2 BALTIC BIRCH
- G (2) 1/2 x 11 1/2 x 8 15/16 BALTIC BIRCH
- H (2) 1/2 x 2 1/2 x 36 BALTIC BIRCH
- I (1) 1/2 x 3 3/4 x 36 BALTIC BIRCH
- J (1) 1/2 x 2 15/16 x 2 1/2 BALTIC BIRCH
- K (1) 1/4 x 16 x 36 TEMPERED HARDBOARD
- L (2) 1/4 x 10 x 4 3/4 TEMPERED HARDBOARD
- M (1) 1/4 x 3 X 36 TEMPERED HARDBOARD
- N (1) 1/4 x 2 1/2 x 2 15/16 TEMPERED HARDBOARD
- O (1) 1/4 x 5/16 x 2 1/2 TEMPERED HARDBOARD



1/2 x 60 x 60 BALTIC BIRCH



1/4 x 24 x 48 TEMPERED HARDBOARD