## 

# **Thank You!**

You have successfully downloaded your document from Workbenchmagazine.com. Below are some tips for Trouble-Free Printing

**1)** Clear printer memory. If you are unable to print this document, turn off your printer for at least 15 seconds and try again.

**2)** Print two or three pages at a time. If clearing the printer memory didn't help, try printing only two or three pages at one time, rather than sending the entire file

**3)** If a document is required to be at an accurate scale set the page scaling option to "none" in your printer settings.

**4)** Get advanced printer help. Visit Adobe Support for instructions in troubleshooting common printer problems.

http://www.adobe.com/support/techdocs/316508.html

## WORKBENCH. ADIRONDACK SET

Issue 260 Volume 56

6 Number 4

July/August 2000

#### **MATERIALS LIST FOR CHAIR & OTTOMAN**

MATERIALS LIS	ST		
MATERIALS LIS A (2) Front Legs B (2) Back Legs C (1) Front Skirt D (1) Lwr Bk Supt E (2) Corner Blocks F (2) Arms G (1) Mid. Bk. Spt. H (1) Up. Bk. Spt.	1½ x 3½ -22 ¾ x 7¼ -38 3¼ x 5½ -22 1½ x 3½ -20½	M (1) Seat Slats N (1) Bk. Seat Slat O (2) 2x4 Legs P (2) Front Legs Q (1) Front Skirt R (5) Slats S (1) Top Slat	<sup>3</sup> / <sub>4</sub> x 3 <sup>1</sup> / <sub>2</sub> -22 <sup>3</sup> / <sub>4</sub> x 3 <sup>1</sup> / <sub>4</sub> -22 1 <sup>1</sup> / <sub>2</sub> x 3 <sup>1</sup> / <sub>2</sub> -15 <sup>1</sup> / <sub>8</sub> <sup>3</sup> / <sub>4</sub> x 7 <sup>1</sup> / <sub>4</sub> -24 <sup>3</sup> / <sub>4</sub> x 3 <sup>1</sup> / <sub>2</sub> -20 <sup>1</sup> / <sub>2</sub> <sup>3</sup> / <sub>4</sub> x 3 <sup>1</sup> / <sub>2</sub> -22 <sup>3</sup> / <sub>4</sub> x 1 <sup>1</sup> / <sub>2</sub> -22
<ul> <li>I (1) Center Slat</li> <li>J (2) Inner Slats</li> <li>K (2) Outer Slats</li> <li>L (2) Brackets</li> </ul>	<sup>3</sup> / <sub>4</sub> x 3 <sup>1</sup> / <sub>2</sub> -33 <sup>3</sup> / <sub>4</sub> x 3 <sup>1</sup> / <sub>2</sub> -32 <sup>1</sup> / <sub>2</sub> <sup>3</sup> / <sub>4</sub> x 3 <sup>1</sup> / <sub>2</sub> -30 <sup>3</sup> / <sub>4</sub> <sup>3</sup> / <sub>4</sub> x 3 -8		

#### **CUTTING DIAGRAM**

1 x 8 - 96						
В			В			
1 x 8 - 96						
Р	Р			G		
1 x 6 - 96						
С	F		F			
2 x 4 - 96			-			
A	А		D	EE		
2 x 4 - 96						
2 x 4 - 96 O	0					
1 x 4 - 96						
Н	Ι			J		L
l x 4 - 96						
J		K			К	
l x 4 - 96						
M	М		М		М	
1 x 4 - 96				(	S	
R	Q		Ν			L
1 x 4 - 96						
R	R		R		R	

### WORKBENCH. ADIRONDACK SET

Issue 260 Volume 56 Number 4

July/August 2000

#### **MATERIALS LIST FOR CHAIR & TABLE**



#### MATERIALS LIST

- A (4) Legs  $1\frac{1}{2}$ " x  $3\frac{1}{2}$ "-16"
- B (2) Side Aprons <sup>3</sup>/<sub>4</sub>" x 3<sup>1</sup>/<sub>2</sub>"-19"
- C (2) End Aprons <sup>3</sup>/<sub>4</sub>" x 3<sup>1</sup>/<sub>2</sub>" -14<sup>1</sup>/<sub>2</sub>"
- D (1) Center Strtch. <sup>3</sup>/<sub>4</sub>" x 3<sup>1</sup>/<sub>2</sub>"-13"
- E (2) Outer Slats <sup>3</sup>/<sub>4</sub>" x 3<sup>1</sup>/<sub>2</sub>" -27"
- F (1) Center Slat  $\frac{3}{4}$ " x  $\frac{3}{2}$ " -30"
- G (2) Inner Slats <sup>3</sup>/<sub>4</sub>" x 3<sup>1</sup>/<sub>2</sub>" -29<sup>1</sup>/<sub>4</sub>"

#### **CUTTING DIAGRAM**

<u>2 x 4 - 96</u>							
A	А	A	A				
<u>1 x 4 - 96</u>			•	·			
В	В	C		С	D		
1 x 4 - 96							
E		Е		F			
1 x 4 - 96							
G		G					