



# Thank You!

---

**You have successfully downloaded your document from Workbenchmagazine.com. Below are some tips for Trouble-Free Printing**

- 1)** Clear printer memory. If you are unable to print this document, turn off your printer for at least 15 seconds and try again.
  
- 2)** Print two or three pages at a time. If clearing the printer memory didn't help, try printing only two or three pages at one time, rather than sending the entire file
  
- 3)** If a document is required to be at an accurate scale set the page scaling option to "none" in your printer settings.
  
- 4)** Get advanced printer help. Visit Adobe Support for instructions in troubleshooting common printer problems.

<http://www.adobe.com/support/techdocs/316508.html>

## MATERIALS LIST

MATERIALS & HARDWARE						
Part	Qty	T	W	L	Material	
A	2	2½"	2½"	43"	Cedar	
B	2	2½"	2½"	29"	Cedar	
C	4	1½"	3"	16½"	Cedar	
D	2	1½"	3¾"	16½"	Cedar	
E	2	1½"	3"	16½"	Cedar	
F	1	1½"	4"	20"	Cedar	
G	2	¾"	3½"	16"	Cedar	
H	3	¾"	4"	18"	Cedar	

**Curved Back Bar Chair Hardware**

- (22) #8 x 1¼" Fh Stainless Steel Woodscrews



## CUTTING DIAGRAM




3½" x 3½" x 96" Cedar



3½" x 3½" x 96" Cedar



1½" x 3½" x 96" Cedar



1½" x 5½" x 96" Cedar



¾" x 5½" x 96" Cedar