# 

# **Thank You!**

You have successfully downloaded your document from Workbenchmagazine.com. Below are some tips for Trouble-Free Printing

**1)** Clear printer memory. If you are unable to print this document, turn off your printer for at least 15 seconds and try again.

**2)** Print two or three pages at a time. If clearing the printer memory didn't help, try printing only two or three pages at one time, rather than sending the entire file

**3)** If a document is required to be at an accurate scale set the page scaling option to "none" in your printer settings.

**4)** Get advanced printer help. Visit Adobe Support for instructions in troubleshooting common printer problems.

http://www.adobe.com/support/techdocs/316508.html

## **VORKBENCH**

Issue # 277 Volume 59 Number 3

## PATIO SWING

**MAY / JUNE 2003** 


## **MATERIAL AND HARDWARE LIST**


#### HARDWARE


- (16) #10 x 3" Stainless Steel Screws
  (10) #10 x 2<sup>1</sup>/<sub>2</sub>" Stainless Steel Screws
- (10) #10 x 2" Stainless Steel Screws (8) #10 x 1<sup>1</sup>/<sub>4</sub>" Stainless Steel Screws (102) #8 x 1<sup>1</sup>/<sub>2</sub>" Stainless Steel Screws
- $(140) \frac{3}{8}$  Wood plugs,  $\frac{5}{16}$  long  $(2) \frac{5}{16} \times \frac{21}{2}$  Screw-Eyes  $(2) \frac{5}{16} \times \frac{41}{2}$  Screw-Eyes

- (4)
- <sup>5</sup>/<sub>16</sub>" x 5" Hook-Bolts #1 Plated Steel Chain Lengths (lengths will vary) ٠ (4)
- ٠ (2) Swing Hangers
- (8) 8d Galvanized Nails
- $^{5}/_{16}$ " Washers  $^{5}/_{16}$ " Lock Nuts ٠ (6)
- (6)

### SWING CONSTRUCTION VIEW








Page 1 of 2 Copyright 2003, August Home Publishing Company. All Rights Reserved.

## WORKBENCH.

Issue # 277 Volume 59 Number 3

#### MAY / JUNE 2003

## **CUTTING DIAGRAM**



**PATIO SWING** 

Copyright 2003, August Home Publishing Company. All Rights Reserved.