



Thank You!

You have successfully downloaded your document from Workbenchmagazine.com. Below are some tips for Trouble-Free Printing

- 1)** Clear printer memory. If you are unable to print this document, turn off your printer for at least 15 seconds and try again.


- 2)** Print two or three pages at a time. If clearing the printer memory didn't help, try printing only two or three pages at one time, rather than sending the entire file

- 3)** If a document is required to be at an accurate scale set the page scaling option to "none" in your printer settings.

- 4)** Get advanced printer help. Visit Adobe Support for instructions in troubleshooting common printer problems.

<http://www.adobe.com/support/techdocs/316508.html>

MATERIALS LIST



MATERIALS & HARDWARE

Part	Qty	T	W	L	Material
A	4	3/4"	3"	11"	Ash
B	4	3/4"	3"	19 1/2"	Ash
C	10	1/2"	1/2"	11"	Ash
D	8	1/2"	1/2"	14 1/2"	Ash
E	4	3/4"	3"	34 1/2"	Ash
F	20	3/4"	3"	11"	Ash
G	4	3/4"	2"	34 1/2"	Ash
H	8	1/4"	1/2"	1 1/8"	Ash



(4) 1 3/16" Dbl. Nail-on Glides (Item #18665) *
 (4) Cross Dowels (Item #31823) *
 (4) 2" Connector Bolts (Item #31849) *

* Items available at 800-233-9359 or www.Rockler.com

CUTTING DIAGRAM

A	A	B	B	E
A	A	B	B	E
E		E		

3/4" x 10" x 96" Ash

G	F	F	F	F	F
G	F	F	F	F	F
G	F	F	F	F	F
G	F	F	F	F	F

3/4" x 12" x 96" Ash



1/2" x 6" x 48" Ash