

Thank You!

You have successfully downloaded your document from Workbenchmagazine.com. Below are some tips for Trouble-Free Printing

- 1) Clear printer memory. If you are unable to print this document, turn off your printer for at least 15 seconds and try again.
- **2)** Print two or three pages at a time. If clearing the printer memory didn't help, try printing only two or three pages at one time, rather than sending the entire file
- **3)** If a document is required to be at an accurate scale set the page scaling option to "none" in your printer settings.
- **4)** Get advanced printer help. Visit Adobe Support for instructions in troubleshooting common printer problems.

http://www.adobe.com/support/techdocs/316508.html

Number 5 October 2006 Issue 297 Volume 62

MATERIALS LIST




MATERIAL LIST							
	Part	Qty	Size	Material			
PLA	PLANER CART						
N	SIDE PANELS	2	¾" x 16½" x 28¼"	Baltic Birch Plywo			
0	SIDE EDGING	4	³ / ₄ " x 1 ¹ / ₂ " x 28 ¹ / ₄ "	Maple			
Р	TOP CAPS	2	³ / ₄ " x 1 ¹ / ₂ " x 17 ¹ / ₂ "	Maple			
Q	CLEATS	2	³⁄4" x 2½" x 16"	Maple			
R	BOTTOM PANEL	1	¾" x 16½" x 25½"	Baltic Birch Plywo			
S	BOTTOM RAILS	2	³⁄4" x 5¹⁄2" x 24"	Maple			
T	TOP PANEL	1	¾" x 16½" x 23"	Baltic Birch Plywo			
U	FRONT/BACK RAILS	2	³⁄4" x 2¹⁄2" x 24"	Maple			
V	SIDE RAILS	2	³ / ₄ " x 2½" x 16½"	Maple			

HARDWARE & PRE-ASSEMBLED ITEMS:

- (16) #8 x 1½" Fh Woodscrews (12) #10 x 3" Fh Screws

- (12) #10 x 3" Fn Screws
 (2) 3/8" Carriage Bolts, 3" long
 (2) 3/8" ID Nylon Sleeves, 2" long
 (2) 3/8" Washers
 (2) 3/8" Nuts
 (2) 2" Barrel Bolts*
 (2) 3" Swivel-Locking Casters*
 (2) 3" Fixed Casters*

CUTTING DIAGRAM




c	c	U	
3	3	U	

3/4" x 6" x 84" Maple

^{** (}Item available at KregTools.com or 800-447-8638)

^{* (}Items available at Lowe's stores. To find a store in your area, visit Lowes.com, or call 800-445-6937)

Issue 297 Volume 62 Number 5 October 2006



 $\frac{3}{4}$ " x 48" x 96" Maple Plywood